## TOPSECRET

25X1

25X1 25X1

25X1

25X1

25X1

25X1

25X1

1729Z 19 JAW 63 25 YEAR RE-REVIEW
DIRECTOR
OPS (1-2-3-4-5) EMERGENCY
S/C (6)
TOR: 1959Z 19 JAN 63 IN 63037
EMERG 0593
REF A 0583
B 150 ·
A. 3213 (DELAYED REPORT)
B. 19/0915Z
C. MSN SUCCESSFUL, WEATHER CLEAR. EQUIP OPN GOOD. LOW LEVEL
FUEL LITE ON AT TANKER HOOK-UP. FUEL CURVE APPROX 100 GAL BELOW
PLANNED CURVE. AFTER SUCCESSFUL REFUEL, LIGHT REMAINED ON. NO
AIR PRESS IN TANK ON LANDING. BELIEVE FLOAT VALVE STUCK. WILL
ADVISE MORE DETAILS ASAP.
D. AT APPROX 0523Z, BOTH LITES ILLUMINATED AND REPEATED
FOR THREE TIMES DURING ONE AND ONE-HALF MIN PD INDICATING STATION
DEAD AHEAD. NOTE: WILL CLARIFY WHEN ARR ON KC-135.
PILOT MADE 90 DEG LEFT TURN AND LOST INDIC. LIGHT AGAIN ILLUMINATED
AT 0630Z. REMAINED ON UNTIL 0700Z WITH INTERMITTENT INDICATION
ON BARELY READABLE. BEARING INFO UNRELIABLE DUE TO PROBABLE
DISTANCE.
END OF MESSAGE

TOPSECRET